

**SPECIFICATION AMENDMENTS:**

Please amend the specification as follows:

Page 12, line 9, through line 14, please amend the current paragraph as follows:

B1  
--As shown in Fig. 4, the cam surface 28 comprises a first slope 29 relatively steeply inclined and a second slope 30 relatively gently inclined, and the second slope 30 corresponds to the rear of a stroke in the locking direction of the lock lever. The adjacent slopes are connected together at a protruding portion that projects toward the cam follower.--